

**Inspection Photos**  
**Location Name:** PETTINGER-66N64W /2NESE  
**Location #:** 305861



**Photo #1**  
**Pettinger 43-2 (05-123-23592) Wellsite**  
**Producing | PR**  
**Weeds**



**Photo #2**  
**Pettinger 43-2 Wellsite**  
**Producing | PR**  
**Weeds appear mitigated**

## Inspection Photos

Location Name: PETTINGER-66N64W /2NESE

Location #: 305861



**Photo #3**

**Pettinger 44-2, 43-2, 33-2, 34-2 Battery**

**Active**  
*prior insp.*



**Photo #4**

**Pettinger 44-2, 43-2, 33-2, 34-2 Battery**

**Active**