

Inspection Photos
Location Name: Latham 21-1
Location ID: 429652



Photo #1 Wellhead & Sign

Inspection Photos
Location Name: Latham 21-1
Location ID: 429652



Photo #2 Tank Battery



Photo #3 Separator & ECD

Inspection Photos
Location Name: Latham 21-1
Location ID: 429652



Photo # 4 Used Rags under scrubber




Photo #5 Used Rags under scrubber