

**Inspection Photos**  
**Location Name: Great Western Sugar Pad**  
**Location ID: 332604**



**Production facility**

**Inspection Photos**  
**Location Name: Great Western Sugar Pad**  
**Location ID: 332604**



**Trash on 9/19/19**



**Trash on 9/30/19**

Inspection Photos  
Location Name: Great Western Sugar Pad  
Location ID: 332604



Trash on 9/19/19



Trash on 9/30/19

Inspection Photos  
Location Name: Great Western Sugar Pad  
Location ID: 332604



Trash on 9/19/19



Trash on 9/30/19

**Inspection Photos**  
**Location Name: Great Western Sugar Pad**  
**Location ID: 332604**



**Master valve and stained soil on 9/19/19**



**Master valve and stained soil on 9/30/19**

**Inspection Photos**  
**Location Name: Great Western Sugar Pad**  
**Location ID: 332604**



**Master valve and stained soil on 9/19/19**



**Master valve and stained soil on 9/30/19**