

Inspection Photos

Loc#334460

Operator: CPX

Inspection Number: 692401375

Inspection Date: 9/23/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

September 23, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: CPX TPR Loc#334460



Photo#2:
Cut Slope at East side of site.



Photo#3:
Base of Cut Slope.

September 23, 2019



Photo#4:
Top of Cut Slope



Photo#5:
Top of Cut Slope.

September 23, 2019



Photo#6:
Reservoir at base of Fill Slope. .



Photo#7:
Materials stockpile.

September 23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: CPX TPR Loc#334460



Photo#8:
Debris, stored supplies.



Photo#9:
Debris, stored supplies.

September 23, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: CPX TPR Loc#334460