

Inspection Photos
Operator: BP America
Location/API #: 067-07233
Date: 9-24-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View of area in the southeastern project area where junk and debris were observed in June 2019.



Photo 4. View of reference area comprised of ponderosa pine forest with oak brush understory.