

Inspection Photos
Location Name: Emerson #3-29J
Location ID: 319508



Photo 1 WH. Well is shut in



Photo 2 Sep/ meter house

Inspection Photos
Location Name: Emerson #3-29J
Location ID: 319508



Photo 3 Unused equipment: unmarked not LOTO risers



Photo 4 TNK BTRY. Crude oil tank visible from public road paint is covered by what appears to be rust