

# *Inspection Photos*

*API#081-07750*

*Operator: PRM*

*Inspection Number: 692401378*

*Inspection Date: 9/12/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
View North over main pad area of Location.



Photo#2:  
View South over main pad area of Location.

September 12, 2019





Photo#3:  
Views over disturbed area to Northwest of main pad location.

September 12, 2019





**Photo#4:**  
Canada thistle and Absinth wormwood on site.

September 12, 2019



**Photo#5:**  
Canada thistle and Absinth wormwood on site





Photo#6:  
Wattles in plastic netting partially buried on site.

September 12, 2019



Photo#7:  
COGCC Map 2013 aerial of Location.

September 12, 2019