

Inspection Photos
Location Name: Milton H Nelson Unit C #1
Location ID: 336262



Photo #1 WH



Photo #2 WH sign updated

Inspection Photos
Location Name: Milton H Nelson Unit C #1
Location ID: 336262



Photo #3 Weeds cut around Electric panel

Photo #4 Noxious weeds cut down at entrance to location