

Inspection Photos
Location Name: Nickerson 4
Location ID: 326976



Photo 1 – Open Wellbore and stained soil




Photo 2 – Unused Chemical tanks, Propane tank and Pumping Unit, Engine Housing

Inspection Photos
Location Name: Nickerson 4
Location ID: 326976



Photo 3 – Unused Engine and chemical tanks



Photo 4 – Trash on the Northeast side of Pumping Unit

Inspection Photos
Location Name: Nickerson 4
Location ID: 326976




Photo 5 – Stained Soil at Wellhead



Photo 6 – Wellhead Sign