

Inspection Photos


API#081-06772

Operator: Beartooth O&G

Inspection #: 692401381

Inspection Date: 9/13/19





Photo#1:

Overview of Location to Southwest. Arrows indicate equipment footprints. Inserts are close ups of ground at bare areas.

September 13, 2019



Photo#2:
GE aerial 2010



Photo#3:
COGCC Map aerial 2017.

September 13, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Beartooth PA Federal API#081-06772



Photo#4:
Close up of equipment footprint area.




Photo#5:
Close up of equipment footprint area..

September 13, 2019



Photo#6:
Access road remains



Photo#7:
Access road Culvert.

September 13, 2019



Inspection Photos: Beartooth PA Federal API#081-06772



Photo#8:
Various bits of debris remain on site.

September 13, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Beartooth PA Federal API#081-06772