

**Inspection Photos**  
**Location Name: Seifkin 11-30H**  
**Location ID: 424135**



**Photo 1 – Pumping Unit**



**Photo 2 – Tank Battery**



**Inspection Photos**  
**Location Name: Seifkin 11-30H**  
**Location ID: 424135**



**Photo 3 – Signs do not reflect current operator or current 24 hour Emergency Contact Info**

**Photo 4 – Signs do not reflect current operator**



# Inspection Photos Location Name: Seifkin 11-30H Location ID: 424135



Photo 5 – Signs do not reflect current operator, Sign at Entrance



Photo 6 – Signs do not reflect current operator



**Inspection Photos**  
**Location Name: Seifkin 11-30H**  
**Location ID: 424135**




**Photo 7 – Signs do not reflect current operator**



**Photo 8 – Unused Separator**

**Inspection Photos**  
**Location Name: Seifkin 11-30H**  
**Location ID: 424135**



**Photo 9 – Stained Soil at the Engine and Exhaust**