

Inspection Photos
Operator: BP America
Location/API #: 067-06536
Date: 9-24-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing, largely with smooth brome and western wheatgrass.



Photo 3. View of reference area vegetation, comprised of open ponderosa pine woodland and grass fields in openings.