

Inspection Photos
Operator: BP America
Location/API #: 067-08629
Date: 9-30-2019



Photo 1 View of the southern project area from the southwestern edge facing eastward. Revegetation is progressing with grasses such as western wheatgrass and smooth brome, as well as young ponderosa pine trees.



Photo 2. View of erosional downcutting (approx. 2 feet wide and deep) occurring along the access road where stormwater controls are needed.



Photo 3. View of reference area vegetation, comprised of open ponderosa pine woodland and shrub/grass understory dominated by gambel oak.