

Inspection Photos  
Operator: BP America  
Location/API #: 067-07176  
Date: 9-30-2019



Photo 1 View of the project area from the southwestern edge facing center.





Photo 2. View of the northern fill slope from the northwestern edge facing westward. Revegetation is progressing in portions of the reclamation areas; largely with smooth brome and sand dropseed. Annual weeds such as prickly lettuce are threatening successful revegetation and need to be managed.





Photo 3. View of reference area vegetation, comprised of open grass field, largely comprised of smooth brome.