

Inspection Photos
Location Name: Nelson E 1 Battery
Location ID: 336337



Photo #1 WH signs

Photo #2 Meter house, ECDs and separator

Inspection Photos
Location Name: Nelson E 1 Battery
Location ID: 336337



Photo #3 TB signs

Photo #4 Separators removed Risers have been marked LOTO

Inspection Photos
Location Name: Nelson E 1 Battery
Location ID: 336337




Photo #5 Stained soil appears to have been addressed

Photo #6 stained soil and leaking WH appear to have been addressed

Inspection Photos
Location Name: Nelson E 1 Battery
Location ID: 336337





Photo #7 Unused risers appear to have been Marked LOTO

Photo #8 Unused risers appear to have been Marked LOTO

Inspection Photos
Location Name: Nelson E 1 Battery
Location ID: 336337




Photo #9 Unused risers appear to have been Marked LOTO

Photo #10 Unused risers appear to have been Marked LOTO