

Inspection Photos
Location Name: Anderson Trust #1
Location ID: 318607



Photo #1 WH doesn't appear TA no flow line connected



Photo #2 Unused unmarked flow line NO LOTO

Inspection Photos
Location Name: Anderson Trust #1
Location ID: 318607



Photo # Access road to location overgrown with weeds.