

Inspection Photos

API: 05-071-06855

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/1/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-06855 | Date: 10/1/2019

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06855 | Date: 10/1/2019

Inspection Photos



Photo 2. Fence around the pit has been partially removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06855 | Date: 10/1/2019

Inspection Photos



Photo 3. Unknown riser line with no LOTO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06855 | Date: 10/1/2019