

Inspection Photos

API: 05-071-08603

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/1/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08603 | Date: 10/1/2019

Inspection Photos



Photo 1. The well sign is missing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08603 | Date: 10/1/2019

Inspection Photos



Photo 2. Vegetation is well established in the interim reclamation area. There are two noxious weeds that should be cut and bagged.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08603 | Date: 10/1/2019

Inspection Photos



Photo 3. Facing toward the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08603 | Date: 10/1/2019