

Inspection Photos
Location Name: Bondad 33-10 #100
API: 05-067-07267



Stained concrete pad and surrounding gravel have been cleaned.



Leaks at hammer unions have been stopped, and stained gravel has been cleaned up.

Inspection Photos
Location Name: Bondad 33-10 #100
API: 05-067-07267



Wellhead and surrounding gravel have been cleaned up.



ASTs were not labeled with NFPA placards at the time of this inspection.