

Inspection Photos
Location Name: Vogl Battery
Location ID: 444612



Photo #1 TB signs



Photo #2 TB

Inspection Photos
Location Name: Vogl Battery
Location ID: 444612



Photo #3 ECD and heated horz. separator

Photo #4 Separators

Inspection Photos
Location Name: Vogl Battery
Location ID: 444612



Photo #5 gas meter run

Photo #6 Wellsite

Inspection Photos
Location Name: Vogl Battery
Location ID: 444612



Photo #7 Wellsite

Photo #8 Wellsite

Inspection Photos
Location Name: Vogl Battery
Location ID: 444612



Photo #9 Wellsite