

# *Inspection Photos*

*API#045-06376*

*Operator: Maralex*

*Inspection: #692401402*

*Inspection Date: 9/27/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to West.


September 27, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376





Photo#2:

View over Blowdown Pit. Insert showing one area of damaged netting

September 27, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376