

Inspection Photos
Location Name: Marconi 1-1H
Location ID: 423680




Photo 1 – Stained Soil at Wellhead



Photo 2 – Stained Soil at the front of Pumping Unit, please dispose of Oil containers.



Inspection Photos
Location Name: Marconi 1-1H
Location ID: 423680




Photo 3 – Stained Soil at Engine



Photo 4 – Stained Soil at Exhaust

Inspection Photos
Location Name: Marconi 1-1H
Location ID: 423680



Photo 5 – Stained Soil at Treater Shed




Photo 6 – Unused Tubing strings

Inspection Photos
Location Name: Marconi 1-1H
Location ID: 423680



Photo 7 – Unused Equipment, storage of Equipment



Photo 8– Unused Equipment, storage of Equipment



Inspection Photos
Location Name: Marconi 1-1H
Location ID: 423680




Photo 9 – Unused Equipment, storage of Equipment



Photo 10 – Unused Equipment, storage of Equipment