

Final Reclamation Inspection

September 25, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 309839

Inspection Document #: 697500630

Weld County, CO

NWNE Section 16 T4N R64W


Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RYANN STATE C #16-27
Location ID: 309839



Aerial imagery taken in 2017. Aerial imagery shows two areas circled in yellow. The Ryann State C 16-27 well was serviced by the northern tank battery circled in yellow.

Inspection Photos

Location Name: RYANN STATE C #16-27

Location ID: 309839



Photo 1. Photo taken from the southern portion of the northern tank battery on May 30, 2019, facing West.



Photo 2. Photo taken from the southern portion of the northern tank battery on May 30, 2019, facing North.

Inspection Photos

Location Name: RYANN STATE C #16-27

Location ID: 309839



Photo 3. Photo taken from the southern portion of the northern tank battery, facing North. Photo illustrates the Operator has started to perform Final Reclamation activities as road base material has been removed. Appears compaction alleviation has been performed. It is unclear whether or not compaction alleviation has been cross-rippled per Rule 1003.c.

Inspection Photos

Location Name: RYANN STATE C #16-27

Location ID: 309839



Photo 4. Photo taken from the northern tank battery, facing West. Operator shall remove the culvert and access point.