

# Final Reclamation Inspection

September 25, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 309896

Inspection Document #: 697500632

Weld County, CO

NENE Section 16 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



Aerial imagery taken in 2017. Aerial imagery shows four areas circled in yellow. The southern tank battery circled in yellow serviced the three circled wells.

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



**Photo 1.** Photo taken from the southern tank battery on May 30, 2019, facing South.

## Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



**Photo 2.** Photo taken from the southern tank battery, facing Southwest. Photo illustrates equipment (i.e., meter house) has been removed. Operator has started to perform Final Reclamation activities. Also, ground monitoring wells have been installed at the location.

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



**Photo 3.** Photo taken from the southern tank battery, facing West. See comments under Photo 2.