

Interim Reclamation Inspection

September 25, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 329335

Inspection Document #: 697500634

Weld County, CO

SWSW Section 10 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RICHARDSON #10-13
Location ID: 329335



Aerial imagery taken in 2011. Aerial imagery shows a disturbance area around the wellhead that is not reflective of reference area vegetation.

Inspection Photos
Location Name: RICHARDSON #10-13
Location ID: 329335



Photo 1. Photo taken adjacent to the well location on May 30, 2019, facing South. Photo illustrates a disturbance that is not reflective of reference area vegetation.



Photo 2. Photo taken adjacent to the well location on May 30, 2019, facing West. See comments under Photo 1.

Inspection Photos
Location Name: RICHARDSON #10-13
Location ID: 329335



Photo 3. Photo taken adjacent to the well location on May 30, 2019, facing East. See comments under Photo 1.



Photo 4. Reference photo taken west of the well location on May 30, 2019, facing West.



Photo 5. Photo taken adjacent to the well location, facing South. Photo illustrates similar vegetative conditions (i.e., disturbance area that is not reflective of reference area vegetation). Operator has failed to respond to the previous complaint filed in May 2018 by contacted the landowner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production.



Photo 6. Close up photo taken from the disturbance area that is not reflective of reference area vegetation.

Inspection Photos
Location Name: RICHARDSON #10-13
Location ID: 329335



Photo 7. Reference photo taken west of the well location, facing West. See comments under Photo 1.