

Inspection Photos
Location Name: Richmond 22-1
Location ID: 327707



Photo 1 – Tank Battery Sign

Photo 2 – Weeds at Tank Battery

Inspection Photos
Location Name: Richmond 22-1
Location ID: 327707



Photo 3 – Weeds at Heater Treater

Photo 4 – Weeds at Wellhead