

Inspection Photos
Location Name: Simpson 24-11
Location ID: 313288



Photo 1. Overview of location taken facing northeast.

Inspection Photos
Location Name: Simpson 24-11
Location ID: 313288



Photo 2. Meter run that has become debris. Unmarked riser on right side of meter run.



Photo 3. Annual weeds on access road.