

Inspection Photos
Location Name: Simpson 24-10
Location ID: 313289



Photo 1. Overview of location facing west. Annual and noxious weeds visible.



Photo 2. Tank label has peeled off.



Inspection Photos
Location Name: Simpson 24-10
Location ID: 313289



Photo 3. Separator equipment stored on location.



Photo 4. Weeds on access road.