

**Inspection Photos**  
**Location Name: Two E Ranch 1-4 pad**  
**Tank Battery ID: 447123**



**Photo #1 Separator, ECD, Meter Run & Weeds on 9/18/19**

**Photo #2 Separator, ECD, Meter Run & Weeds on 10/4/19**

Inspection Photos  
Location Name: Two E Ranch 1-4 pad  
Tank Battery ID: 447123



**Photo #3 Weeds grown around separator on 9/18/19**

**Photo #4 Weeds grown around separator on 10/4/19**

**Inspection Photos**  
**Location Name: Two E Ranch 1-4 pad**  
**Tank Battery ID: 447123**



**Photo #5 Weeds grown around crude oil tank on 9/18/19**

**Photo #6 Weeds grown around crude oil tank on 10/4/19**

**Inspection Photos**  
**Location Name: Two E Ranch 1-4 pad**  
**Tank Battery ID: 447123**



**Photo #7 Weeds grown around produce water tank on 9/18/19**

**Photo #8 Weeds grown around produce water tank on 10/4/19**