

Final Reclamation Inspection

September 25, 2019

Operator: NOBLE ENERGY INC- #100322

Location ID: 330388

Inspection Document #: 697500638

Weld County, CO

NWNW Section 36 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE CLARK #36-22
Location ID: 330388



Photo 1. Photo taken from the southern tank battery, facing Northwest. Photo illustrates the Operator has performed Final Reclamation activities with the evidence of drill rows, straw mulch and germination.

Inspection Photos
Location Name: STATE CLARK #36-22
Well Location ID: 330388



Photo 2. Photo taken from the northern battery location, facing North. Operator has failed to remove all equipment from the location.



Photo 3. Photo taken from the northern battery location, facing North. Photo illustrates Operator has performed Final Reclamation activities around the remaining equipment.