

Final Reclamation Inspection

September 25, 2019

Operator: NOBLE ENERGY INC- #100322

Location ID: 323685

Inspection Document #: 697500640

Weld County, CO

SWNE Section 36 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE FARM #36-7
Location ID: 323685



Photo 1. Photo taken east of the well location, facing West. Photo illustrates the Operator has failed to remove equipment.