

Inspection Photos
Location Name: Gollner 27-43
Location ID: 331272



Production facility



Wellhead

Inspection Photos
Location Name: Gollner 27-43
Location ID: 331272



Crude oil tank berm



Crude oil tank berm

Inspection Photos
Location Name: Gollner 27-43
Location ID: 331272



Lease road erosion



Lease road erosion

Inspection Photos
Location Name: Gollner 27-43
Location ID: 331272



Lease road erosion



Lease road erosion

Inspection Photos
Location Name: Gollner 27-43
Location ID: 331272



Lease road erosion