

Schmid Properties INC, Clark 8-35
121-08561

Inspection #688305871

9/24/2019

Routine Inspection



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Colorado Oil and Gas Conservation Commission
40.18594, -103.15574, 4507.9ft, 290°
09/24/2019 12:09:33 PM



Colorado Oil and Gas Conservation Commission
40.18593, -103.15575, 4511.2ft, 278°
09/24/2019 12:09:35 PM



Colorado Oil and Gas Conservation Commission
40.18589, -103.15589, 4517.7ft, 43°
09/24/2019 12:10:29 PM



Colorado Oil and Gas Conservation Commission
40.18598, -103.1558, 4521.0ft, 116°
09/24/2019 12:10:10 PM



SCHMID PROPERTIES INC.
CLARK LEASE
SEC.35-T3N-R52W
WASHINGTON CO., COLORADO
EMERGENCY PHONE (970)-345-6550

SCHMID PROPERTIES INC.
CLARK 2-35, 7-35, 8-35, 10-35
NWSE SEC 35 T3N R52W
ACCESS CO RD FF
IN CASE OF EMERGENCY
CALL (337) 261-1500
OR (970) 554-1988
OR 911

Colorado Oil and Gas Conservation Commission
40.18594, -103.1529, 4524.3ft, 300°
09/24/2019 12:12:19 PM



Colorado Oil and Gas Conservation Commission
40.18595, -103.15291, 4521.0ft, 315°
09/24/2019 12:12:24 PM



Colorado Oil and Gas Conservation Commission

40.18598, -103.15312, 4517.7ft, 30°

09/24/2019 12:12:46 PM

Tank labels are
worn.

Colorado Oil and Gas Conservation Commission
40.18616, -103.15297, 4511.2ft, 336°
09/24/2019 12:13:21 PM



Small hole in
fiberglass tank.

Colorado Oil and Gas Conservation Commission
40.18625, -103.15304, 4507.9ft, 13°
09/24/2019 12:14:03 PM



Colorado Oil and Gas Conservation Commission

40-18632, -103-15307, 4524.3ft, 243°

09/24/2019 12:15:49 PM



Colorado Oil and Gas Conservation Commission

40.18624, -103.15299, 4521.0ft, 2°

09/24/2019 12:13:29 PM



Colorado Oil and Gas Conservation Commission
40.18653, -103.15303, 4504.6ft, 30°
09/24/2019 12:15:08 PM



Colorado Oil and Gas Conservation Commission
40.18599, -103.15304, 4511.2ft, 136°
09/24/2019 12:16:46 PM