

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 3: Wellhead Sign



Photo 4: Wellhead

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 5: Stained soil



Photo 6: Wellhead Sign



Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 7: Wellhead



Photo 8: Wellhead Sign

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 9: Wellhead



Photo 10: Tank Battery Sign

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



**Photo 11: Tank Battery, Inadequate containment
surrounding tank battery**



Photo 12: Tanks NOT anchored

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 13: Separator NOT anchored



Photo 14: No NFPA placard, BBLS faded on H2O tank

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 15: Stained soil removed.

