

Inspection Photos  
Location Name: Great Western Pad 9  
Location ID: 333296



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos  
Location Name: Great Western Pad 9  
Location ID: 333296



Colorado Oil and Gas Conservation Commission  
40.45876, -104.8814, 1438.3m, 7°  
Oct 3, 2019 13:39:52

Photo 3: Wellhead Sign



Colorado Oil and Gas Conservation Commission  
40.45876, -104.88141, 1439.6m, 336°  
Oct 3, 2019 13:40:01

Photo 4: Wellhead

Inspection Photos  
Location Name: Great Western Pad 9  
Location ID: 333296



Photo 5: Wellhead Sign



Photo 6: Wellhead

Inspection Photos  
Location Name: Great Western Pad 9  
Location ID: 333296



Colorado Oil and Gas Conservation Commission  
40.45877, -104.88157, 1436.5m, 360°  
Oct 3, 2019 13:40:42

Photo 7: Wellhead Sign



Colorado Oil and Gas Conservation Commission  
40.45876, -104.88158, 1437.6m, 341°  
Oct 3, 2019 13:40:51

Photo 8: Wellhead

Inspection Photos  
Location Name: Great Western Pad 9  
Location ID: 333296



Colorado Oil and Gas Conservation Commission  
40.45877, -104.88164, 1436.7m, 352°  
Oct 3, 2019 13:41:05

Photo 9: Wellhead Sign



Colorado Oil and Gas Conservation Commission  
40.45876, -104.88166, 1436.2m, 339°  
Oct 3, 2019 13:41:13

Photo 10: Wellhead

Inspection Photos  
Location Name: Great Western Pad 9  
Location ID: 333296



Photo 11: Location



Photo 12: Tank Battery Sign

Inspection Photos  
Location Name: Great Western Pad 9  
Location ID: 333296



Photo 13: Tank Battery



Photo 14: No NFPA placard on produced water tank

**Inspection Photos**  
**Location Name: Great Western Pad 9**  
**Location ID: 333296**



Colorado Oil and Gas Conservation Commission  
40.45821, -104.88118, 1434.2m, 235°  
Oct 3, 2019 13:44:25

**Photo 15: Trash/debris near separator**