

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-07203**  
**Date: 9-30-2019**



Photo 1 View of the project area from the northeastern corner facing center.



Photo 2. View of deceased rabbit on the well pad.




Photo 3. View of trash and debris on the well pad.



Photo 4. View of southern portion of the project area, largely comprised of smooth brome and young ponderosa pine trees.