


Inspection Photos  
Location Name: Spicer 3-32H  
Location 324754



Location 324754



Tank battery rebuilt.

Inspection Photos  
Location Name: Spicer 3-32H  
Location 324754



Line and bermed tank battery, view is to the South.



Lined bermed tank battery.

Inspection Photos  
Location Name: Spicer 3-32H  
Location 324754



**Leaking hammer union between the two southern most tanks.**



**Apparent oily stained soil near the northwest corner of the tank battery.**

**Inspection Photos**  
**Location Name: Spicer 3-32H**  
**Location 324754**



**Equipment and soil stockpile.**



**5-gallon pail with oily rag.**

**Inspection Photos**  
**Location Name: Spicer 3-32H**  
**Location 324754**



**View is looking east, piping within secondary containment.**



**Stainless steel line (trash/debris).**