

Inspection Photos
Location Name: North Platte /14-36
Location #: 428456



Photo #1
North Platte 14-36 (05-123-35367) Wellsite
Shut-In | SI
prior insp.



Photo #2
North Platte X-D-35HZ (05-123-35443) Wellsite
Producing | PR
prior insp.

Inspection Photos
Location Name: North Platte /14-36
Location #: 428456



Photo #3
Latham F-J-1HZ (05-123-35441) Wellsite
Shut-In | SI
prior insp.



Photo #4
North Platte 14-36, X-D-35HZ Battery
Latham F-J-35HZ
Active
prior insp.

Inspection Photos
Location Name: North Platte /14-36
Location #: 428456



Photo #5
North Platte 14-36, X-D-35HZ Compressors
Latham F-J-35HZ
Active
prior insp.

Inspection Photos
Location Name: North Platte /14-36
Location #: 428456



Photo #6
North Platte 14-36, X-D-35HZ Battery
Latham F-J-35HZ
Crude oil tanks 2, 3
Stained soil
prior insp.



Photo #7
North Platte 14-36, X-D-35HZ Battery
Latham F-J-35HZ
Crude oil tanks 2, 3
Stained soil NOW appears mitigated

Inspection Photos
Location Name: North Platte /14-36
Location #: 428456



Photo #8
North Platte 14-36, X-D-35HZ Battery
Latham F-J-35HZ
Crude oil tanks 3, 4
Stained soil
prior insp.



Photo #9
North Platte 14-36, X-D-35HZ Battery
Latham F-J-35HZ
Crude oil tanks 3, 4
Stained soil NOW appears mitigated