

Inspection Photos
Location Name: Suckla Brown Unit 16
Location ID: 318309



Pic 1 pumping unit not connected to rods/horses head on ground



Pic 2 stained soil/mechanical issue

Inspection Photos
Location Name: Suckla Brown Unit 16
Location ID: 318309



Pic 3 sucker rods, and tubing laying next to pumping unit



Pic 4 electric boxes