

Inspection Photos
Location Name: Robert G Burge #2
Location ID: 318501



Photo 1 WH and PU. KPK installed a sticker on sign to make it visible.



Photo 2 it appears weeds, stained soil and mechanical issues have been addressed.