

Final Reclamation Inspection

September 26, 2019

Operator: ANADARKO E&P ONSHORE LLC - #2800

API: 05-123-31795

Inspection Document #: 697500644

Weld County, CO

NWNW Section 1 T8N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HOBART #8-67-1-4H
API: 05-123-31795



Photo 1. Photo taken from the approximate central location, facing East. Photo illustrates weed maintenance is needed, as Kochia and a high abundance of cheatgrass were observed. The presence of desirable species was observed underneath the weeds.

Inspection Photos
Location Name: HOBART #8-67-1-4H
API: 05-123-31795



Photo 2. Photo taken along the southern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: HOBART #8-67-1-4H
API: 05-123-31795




Photo 3. Photo taken along the eastern location, facing North. Photo illustrates the reference area vegetation to the right of the red-dashed line and the disturbance area to the left of the red-dashed line.

Inspection Photos
Location Name: HOBART #8-67-1-4H
API: 05-123-31795




Photo 4. Photo taken along the northern location, facing West. See comments under Photo 3.