

Final Reclamation Inspection

September 26, 2019

Operator: ANADARKO E&P ONSHORE LLC - #2800

API: 05-123-31811

Inspection Document #: 697500646

Weld County, CO

NESW Section 1 T8N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HOBART #8-67-1-11
API: 05-123-31811



Photo 1. Photo taken from the western access road, facing East. Photo illustrates weed maintenance is needed, as Kochia was observed. The presence of desirable species was observed.

Inspection Photos
Location Name: HOBART #8-67-1-11
API: 05-123-31811



Photo 2. Photo taken from the central access road, facing East. See comments under Photo 1.