

# Final Reclamation Inspection

September 26, 2019

Operator: ANADARKO E&P ONSHORE LLC - #2800

API: 05-123-33866

Inspection Document #: 697500648

Weld County, CO

NENW Section 5 T8N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CHRISTNER #8-66-5-3XH  
API: 05-123-33866



**Photo 1.** Photo taken from the western location, facing East. Photo is trying to illustrate the lack of crop establishment (wheat). Crop establishment was bare throughout much of the location.



Inspection Photos  
Location Name: CHRISTNER #8-66-5-3XH  
API: 05-123-33866



**Photo 2.** Photo taken from the western location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: CHRISTNER #8-66-5-3XH  
API: 05-123-33866



**Photo 3.** Photo taken from the eastern location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: CHRISTNER #8-66-5-3XH  
API: 05-123-33866



**Photo 4.** Photo taken from the northern location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: CHRISTNER #8-66-5-3XH  
API: 05-123-33866



**Photo 5.** Reference photo taken from the western location, facing West. Photo illustrates wheat stubble but illustrates the difference in establishment vs the location.