

Inspection Photos
Operator: BP America
Location/API #: 067-07234
Date: 9-30-2019



Photo 1 View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Fill slope is comprised largely of grasses such as western wheatgrass and sand dropseed.



Photo 3. View of reference area vegetation comprised of a mosaic of ponderosa pine, gambel oak, and open grass fields.