

Inspection Photos
Operator: BP America
Location/API #: 067-08336
Date: 9-30-2019



Photo 1. View of the project area from the well pad entrance.



Photo 2. View of the eastern fill slope from the well pad entrance facing northward. Revegetation is progressing with grasses such as western wheatgrass and smooth brome.



Photo 3. View of reference area vegetation comprised of a mosaic of ponderosa pine, gambel oak, and open grass fields.