

Interim Reclamation Inspection

September 25, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 425070

Inspection Document #: 697500654

Weld County, CO

NWNE Section 8 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RUFF C /08-27D
Location ID: 425070



Aerial imagery taken in 2017. Aerial imagery shows the two culverts needing maintenance.

Inspection Photos
Location Name: RUFF C /08-27D
Location ID: 425070



Photo 1. Photo taken from the eastern access entrance. Photo illustrates stormwater maintenance is required as the culvert is not in proper functioning condition.

Inspection Photos
Location Name: RUFF C /08-27D
Location ID: 425070



Photo 2. Photo taken from the western access entrance. See comments under Photo 1.