

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336




Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Colorado Oil and Gas Conservation Commission
40.46841, -104.7964, 1422.8m, 261°
Oct 7, 2019 14:12:45


Photo 3: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.4684, -104.79637, 1424.7m, 250°
Oct 7, 2019 14:12:59

Photo 4: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Colorado Oil and Gas Conservation Commission
40.46835, -104.79637, 1426.2m, 256°
Oct 7, 2019 14:13:14

Photo 5: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.46835, -104.79637, 1426.2m, 256°
Oct 7, 2019 14:13:23

Photo 6: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Photo 7: Wellhead Sign



Photo 8: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Photo 9: Wellhead Sign



Photo 10: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Photo 11: Wellhead Sign



Photo 12: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336




Photo 13: Wellhead Sign



Photo 14: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Photo 15: Wellhead Sign



Photo 16: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Photo 17: Wellhead Sign



Photo 18: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Colorado Oil and Gas Conservation Commission
40.4678, -104.7964, 1425.2m, 275°
Oct 7, 2019 14:31:45

Photo 19: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.4678, -104.79637, 1424.9m, 258°
Oct 7, 2019 14:31:50

Photo 20: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Photo 21: Wellhead Sign



Photo 22: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Photo 23: Wellhead Sign



Photo 24: Wellhead

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Photo 25: Location Sign



Photo 26: Tank Battery

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Photo 27: Buried vault WITHOUT signage



Photo 28: Buried vault WITHOUT signage

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Colorado Oil and Gas Conservation Commission
40.46699, -104.79688, 1424.0m, 27°
Oct 7, 2019 14:49:42

Photo 29: Buried vault WITHOUT signage/ bucket of unknown contents



Colorado Oil and Gas Conservation Commission
40.46699, -104.79682, 1425.0m, 75°
Oct 7, 2019 14:49:29

Photo 30: Trash inside separator berm

Inspection Photos
Location Name: Hood-Doles 37-20 PAD
Location ID: 449336



Photo 31: Trash inside separator berm