

Inspection Photos
Location Name: Federal 1-15
Location ID: 322388
Inspection Date: September 10, 2019



Photo #1 – Aerial view of the location. The black drop represents the spill on location, the red cross represents remediation 11304 and the white squares represent pits 112128, 112129 and 112130 (stacked on top of each other).



Photo #2 – Location sign.



Inspection Photos
Location Name: Federal 1-15
Location ID: 322388
Inspection Date: September 10, 2019



Photo #3 – Unlabeled stock tank east of vertical separator.



Photo # - Unlabeled stock tank east of horizontal separator.



Inspection Photos
Location Name: Federal 1-15
Location ID: 322388
Inspection Date: September 10, 2019



Photo #5 – Stained soil beneath vertical separator.



Photo #6 – View of the 20 feet by 20 feet by 5 feet deep pit looking south.



Inspection Photos
Location Name: Federal 1-15
Location ID: 322388
Inspection Date: September 10, 2019



**Photo #7 – View of the pit 15 feet by 15 feet by 2 feet deep
pit located north of the horizontal heated separator.**



**Photo #8 – View of the pit 10 feet by 10 feet by 3 feet deep
pit located east of the vertical separator.**

