

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Colorado Oil and Gas Conservation Commission
40.44924, -104.71913, 1402.2m, 25°
Oct 8, 2019 16:22:01

Photo 3: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.44923, -104.71915, 1402.6m, 28°
Oct 8, 2019 16:22:06

Photo 4: Wellhead

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Colorado Oil and Gas Conservation Commission
40.44931, -104.71915, 1399.4m, 35°
Oct 8, 2019 16:22:20


Photo 5: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.44928, -104.71917, 1400.5m, 33°
Oct 8, 2019 16:22:29

Photo 6: Wellhead

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Colorado Oil and Gas Conservation Commission
40.44938, -104.71913, 1399.9m, 29°
Oct 8, 2019 16:22:47

Photo 7: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.44938, -104.71916, 1400.1m, 50°
Oct 8, 2019 16:22:54

Photo 8: Wellhead

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Photo 9: Wellhead Sign



Photo 10: Wellhead

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Photo 11: Wellhead Sign



Photo 12: Wellhead

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Photo 13: Wellhead Sign




Photo 14: Wellhead

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Colorado Oil and Gas Conservation Commission
40.44967, -104.71914, 1401.2m, 15°
Oct 8, 2019 16:24:08

Photo 15: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.44967, -104.71916, 1401.6m, 34°
Oct 8, 2019 16:24:15

Photo 16: Wellhead

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Photo 17: Location (facing SW)



Photo 18: Trash west of wellheads (picture taken facing SW)

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Photo 19: Tank Battery



Photo 20: Trash in tank battery berm (north)

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Photo 21: Trash/Unused risers