

Inspection Photos
Location Name: Latham 41-1 Pad
Tank Battery ID: 468441



Photo # Oily water in containment for Compressor oil tank.
On 9/30/19



Photo # Oily water in containment for Compressor oil tank.
On 10/9/19

Inspection Photos
Location Name: Latham 41-1 Pad
Tank Battery ID: 468441



Photo # Used Rags around pit. On 9/30/19



Photo # Used Rags around pit. On 10/9/19



Inspection Photos
Location Name: Latham 41-1 Pad
Tank Battery ID: 468441



Photo # Oily waste. Stained soil appears at crude oil tanks in multiple areas. On 9/30/19



Photo # Oily waste. Stained soil appears at crude oil tanks in multiple areas. On 10/9/19

Inspection Photos
Location Name: Latham 41-1 Pad
Tank Battery ID: 468441



Photo # Oily waste. Stained soil appears at crude oil tanks in multiple areas. On 9/30/19



Photo # Oily waste. Stained soil appears at crude oil tanks in multiple areas. On 10/9/19

Inspection Photos
Location Name: Latham 41-1 Pad
Tank Battery ID: 468441



Photo # Oily waste. Stained soil appears at crude oil tanks in multiple areas. On 9/30/19



Photo # Oily waste. Stained soil appears at crude oil tanks in multiple areas. On 10/9/19

Inspection Photos
Location Name: Latham 41-1 Pad
Tank Battery ID: 468441



Photo # Oily waste. Stained soil appears at crude oil tanks in multiple areas. On 9/30/19



Photo # Oily waste. Stained soil appears at crude oil tanks in multiple areas. On 10/9/19